

April 25th, 2022

Boston Conservation Commission City Hall Plaza, Room 709 Boston, MA 02201

## Re: IBEW LOCAL 103 Wetland and Buffer Restoration Plan Updates

Dear Commissioners:

*Howard Stein Hudson (HSH)* is providing this letter update to address comments provided by Conservation Commission Staff in relation to the wetland restoration at the IBEW 103 SITE LOCATED AT 256 Freeport Street, Boston, MA. Also attached is an updated wetland impacts plan and the wetland restoration plan.

Comment No.1: Table 1-1 details the calculated impacts to the wetland resources but only quantifies the amount of fill placed within the ILSF. Having been to the site, a substantial amount of fill has also been placed within the IVW and Buff Zone. Why has that not been quantified?

**Response:** HSH has quantified the fill within the IVW & the 100-Foot Buffer Zone. An updated table is provided below. An updated wetland impact plan is also attached.

AREA	SQUARE FEET	CUT (CY)	FILL (CY)
ISOLATED VEGATED WETLAND	1,924	-	10
ISOLATED LAND SUBJECT TO FLOODING	4,929	14	108
100FT WETLAND BUFFER	24,611	311	601

Table 1-1 Resource Area Impacts (Revised 4.25.2022)

**Comment No.2:** The plan itself seems to question the overall survivability of the restoration plantings, especially with the strong presence of invasive species. Why does the plan not include treatment of the invasive species and or restoration of these areas as well?

**Response:** Implementing an invasive plant removal plan across the entire site is a massive undertaking and out of the scope of the enforcement order. In the plan we state that the restoration areas will be monitored for invasives and a treatment will be prepared at that time.



**Comment No.3:** Staff feels that this plan is a good first draft but has noted several components that are missing but overall critical to the success of a restoration effort, A clear understanding of what the overall goals and what the intended end point of the restoration plan is critical in assessing the success of the plan and whether the Resource Area Values have been restored.

**Response:** The goal of the plan is to restore the pre-existing topography and flood storage capacity of the resource area, and to provide an enhanced and more diverse vegetative community than what existed prior to the unpermitted alteration.

Comment No.4: Since we are already in April, a detailed timeline of the fill removal and planting process is necessary to ensure that activities are occurring in the correct sequence and during the correct time of year.

**Response:** The removal of fill will begin in June, 2022. Once the fill is removed the area will be prepared for the seed mixes to be placed. The PWS will inspect for invasive species as outlined in the Wetland and Buffer Restoration Plan prepared by Lucas Environmental, LLC dated March 15, 2022. The erosion control measures, and the disturbed areas will be inspected in accordance with the Stormwater Pollution Prevention Plan. It is anticipated that the trees and shrubs will be planted at the appropriate time in late summer/early fall, depending on weather conditions. Plantings will commence under the supervision of the PWS.

**Comment No.5:** Additional detail on how the fill will be removed and with what equipment, how the predisturbance substrate will be identified, and what process is in place should the predisturbance substrate not be differentiated from the fill.

**Response:** Once the erosion controls are in place and the supervising Professional Wetland Scientist (PWS) is on site the contractor shall use a mid-sized excavator to remove the fill material. The excavator will be positioned outside of the wetland resource areas at all times and will be able to reach all of the filled areas. The fill material will be paced within a 10-wheeler dump truck and removed to the predetermined storage area within the existing parking lot, outside of the wetland resource buffer areas.

The fill material placed with the resource areas consist of roughly graded crushed rock and stone which is fairly easy to identify. The underlining material on the site is the original soil material. Once the PWS visually identifies the underlying native material the use of hand tools will begin to remove the last of the fill material.

Comment No.6: Additional detail on what will happen to the fill, how it will be managed once removed, where it will be stockpiled and/or disposed of, etc.



**Response:** The fill material removed form the resource areas will be stockpiled with the existing parking lot with the appropriate erosion controls (Haybales) in place outside of the wetland buffer areas. Suitable fill will be reused in the construction of the new parking areas. The remainder of the fill material with be trucked off site and dispose of according to State Regulations.

Comment No.6: Additional information on how the plantings will be maintained after planting (including irrigation, weeding, etc.).

**Response:** The PWS will inspect the planting area at the end of the 2022 growing season for invasive species to determine the presence/extent of invasive/opportunistic species within the planting area. If invasive/opportunistic species are found, a control plan including measures for removal will be developed and submitted to the Conservation Commission for review and approval prior to implementation. The control plan will provide for long-term maintenance activities within the restoration areas and Buffer.

The contractor will be required to maintain adequate moisture for the first growing season following planting to support the plantings (>75% survival is required). Irrigation practices will be likely be necessary for the mitigation areas following planting and seeding.


Once the fill is removed from the impacted areas the seed mixes can be placed. These areas would be irrigated twice a week by the contractor or as needed depending on weather conditions. The shrubs and tree planning will be installed in cooler conditions in early fall and will be watered weekly. The watering schedule is subject to change based on weather conditions.


If you have any questions, please do not hesitate to contact me at 617-797-9190 or jdowning@hshassoc.com.

Sincerely,

James Downing

Manager of Civil Engineering





Common Name	Latin Name	Indicator Status	Size	Quantity
Trees			J.,,,,,,,,,,	
Green Ash	Fraxinus pensylvanica	FACW	4-6'	10
Pin Oak	Quercus palustris	FACW	4-6'	6
Red Maple	Acer rubrum	FAC	4-6'	6
		•	Total	22
Shrubs				
Speckled Alder	Alnus rugosa	FACW	2-3'	12
Elderberry	Sambucus canadensis	FACW	2-3'	12
Silky Dogwood	Cormus amomum	FACW	2-3*	12
Pussy Willow	Salix discolor	FACW	2-3'	12
			Total	48

TABLE 2 ILSF AND BUFFER ZONE RESTORATION PLAN PLANTING SCHEDULE			
Common Name	Latin Name	Size	Quantity
Trees		<u> </u>	
Hackberry	Celtis occidentalis	4-6'	6
Red Cedar	Juniperus virginiana	4-6'	10
Chokecherry	Prunus virginiana	4-6'	10
Pin Oak	Quercus palustris	4-6'	8
Gray Birch	Betula populifolia	4-6	6
	THE ALL PROPERTY OF THE PROPER	Total	40
Shrubs			
Black Chokeberry	Aronia melanocarpa	2-3'	25
Bayberry	Myrica pensylvanica	2-3'	25
Virginia Rose	Rosa virginiana	2-3	10
Alternate-leaved Dogwood	Cornus alterniflora	2-3'	15
Serviceberry	Amelanchier canadensis	2-3'	25
		Total	100
Ground Cover			
New England Conservation/	Wildlife Mix, or equivalent	1 lb./7,500 sq. ft.	1.5

TABLE 3 NEW ENGLAND CONSERVATION/WILDLIFE MIX			
Latin Name	Species	Indicator Status	
Elymus virginicus	Virginia Wild Rye	FACW-	
chizachyrium scoparium	Little Bluestem	FACU	
Andropogon gerardii	Big Bluestem	FAC	
Festuca rubra	Creeping Red Fescue	FACU	
Panicum virgatum	Switch Grass	FAC	
hamaecrista fasciculata	Partridge Pea	FACU	
<sup>p</sup> anicum clandestinum	Deer Tongue	FAC+	
Sorghastrum nutans	Indian Grass	UPL	
Asclepias syriaca	Common Milkweed	FACU-	
Heliopsis helianthoides	Ox Eye Sunflower	UPL	
Eupatorium purpureum	Purple Joe Pye Weed	FAC	
Euthamia graminifolia	Grass Leaved Goldenrod	FAC	
Verbena hastata	Blue Vervain	FACW	
Zizia aurea	Golden Alexanders	FAC	
Aster umbellatus	Flat Topped/Umbrella Aster	FACW	
Solidago juncea	Early Goldenrod	NI	

Species	Latin Name	Indicator Status
Fox Sedge	Carex vulpinoidea	OBL
Blunt Broom Sedge	Carex scoparia	FACW
Lurid Sedge	Carex lurida	OBL
Hop Sedge	Carex lupulina	OBL
Fowl Bluegrass	Poa palustris	FACW
Beggar Ticks	Bidens frondosa	FACW
Green Bulrush	Scirpus atrovirens	OBL
Swamp Milkweed	Asclepias incarnata	OBL
Fringed Sedge	Carex crinita	OBL
Soft Rush	Juncus effusus	FACW±
Starved/Calico Aster	(Symphyotrichum lateriflorum)	FACW
Blue Flag	Iris versicolor	OBL
American Mannagrass	Glyceria grandis	OBL
Square Stemmed Monkey Flower	Mimulus ringens	OBL
Spotted Joe Pye Weed	Eupatorium maculatum	OBL




11 Beacon Street, Suite 1010 Boston, MA 02108 www.hshassoc.com

PREPARED FOR:

FREEPORT STREE

RE\	REVISIONS:					
NO	BY	DATE	DESCRIPTION			



PERMIT SET
NOT FOR CONSTRUCTION

## WETLAND AND BUFFER RESTORATION PLAN

DATE:	04/25/22	
PROJECT NUMBER:	19059	
DESIGNED BY:	RJM	
DRAWN BY:	RJM	
CHECKED BY:	JD	
FIG-1		